



European Aviation Safety Agency

The Quality Manager
**BANYAN AIR SERVICE
AVIONICS DIVISION**
5360 NW 20Th Terrace
Fort Lauderdale, Florida 33309
United States of America
Fax N°: +1 954 491 6958

Cologne, 15 March 2011

Ref. Letter: EASA D(2011)/L9b/Rev 1/EASA.145.4281/FAA.SD4R514M/51740

Subject: Changes and Continued validity of EASA Part-145 approval

Dear Sir or Madam,

Following a positive recommendation from the **FAA** the European Aviation Safety Agency hereby accepts the changes and confirms the continued validity of your EASA Part-145 approval until **01 August 2012**, subject to continued compliance with FAR 145 and the EASA special conditions as detailed in the Bilateral Aviation Safety Agreement (BASA) and associated Maintenance Implementation Procedures (MIP):

BANYAN AIR SERVICE AVIONICS DIVISION

EASA Part-145 Approval certificate reference number:

EASA.145.4281

Please find enclosed your amended certificate. This certificate supersedes your EASA.145.4281 approval certificate dated 21 August 2006 which should be returned to the Agency at the following address:

**EASA (European Aviation Safety Agency)
Postfach 10 12 53
50452 Köln
GERMANY**

You are reminded that you are required to submit the necessary documentation to your supervising FAA District Office at least 60 days prior to the end of the next two year continuation cycle of the EASA Part-145 Approval in accordance with the MIP-G¹ which is available on our web site at <http://www.easa.europa.eu>.

Yours faithfully,

Wilfried SCHULZE
Head of Organisations

¹ Guidance material for the US/European Bilateral Aviation Safety Agreement (BASA) and Maintenance Implementation Procedures (MIP). The MIP-G is published on the EASA web site at <http://www.easa.europa.int> under the maintenance page



APPROVAL CERTIFICATE

REFERENCE EASA.145.4281

Taking into account the provisions of Article 12 (2) of Regulation (EC) 216/2008 of the European Parliament and of the Council and the bilateral agreements currently in force between European Union Member States and the Government of the United States of America, the European Aviation Safety Agency (EASA) hereby certifies:

BANYAN AIR SERVICE AVIONICS DIVISION

FAA NUMBER: SD4R514M
5360 NW 20Th Terrace
Fort Lauderdale, Florida 33309
United States of America

as a Part-145 maintenance organisation approved to maintain the products listed in the FAA Air Agency Certificate and associated Operations Specifications and issue related certificates of release to service using the above reference, subject to the following conditions:

1. The scope of the approval is limited to that specified on the FAR Part 145 repair station Air Agency Certificate, and the associated Operations Specifications for work carried out in the USA (unless otherwise agreed in a particular case by EASA).
2. This approval requires continued compliance with FAR Part 145 and the differences as specified in the Maintenance Implementation Procedures, including the use of the FAA Form 8130-3 for release/return to service of components up to and including powerplants.
3. Certificates of return to service must quote the EASA Part-145 approval reference number quoted above and the FAR Part 145 Air Agency Certificate number.
4. Subject to compliance with the foregoing conditions, this approval shall remain valid for an unlimited duration until the approval is surrendered, superseded, suspended or revoked.

Date of issue: 03 January 2011

Signed

For EASA

