



DueList Report

TBM 940

S/N 1407 N940LG

OWNER: LOVE AMERICA, LLC
 ADDRESS: 720 S. POWERLINE RD. STE. D
 DEERFIELD BEACH FL 33442
 OFFICE: 954-732-3990
 FAX:

OPERATOR: LOVE AMERICA, LLC
 ADDRESS: 720 S. POWERLINE RD. STE. D
 DEERFIELD BEACH FL 33442
 OFFICE: 954-732-3990
 FAX:

ANALYST: PETER GONZALEZ
 EMAIL: PGONZALEZ@CAMPSYSTEMS.COM

877-411-CAMP (2267) (OFFICE)
 631-588-3200 (OFFICE)
 WWW.CAMPSYSTEMS.COM

800-787-9749 (EFAX-CARDS)
 631-980-4222 (FAX)

PROJECTED: 12 MOS. to 23-JAN-2025

AIRCRAFT	SERIAL/REGNO: 1407/N940LG	MODEL: TBM 940	MANUFACTURER: DAHER
	CERTIFICATION DATE: 04-JAN-2022	LAST ACTUALS:	PROJECTED:
		330.08 A/C HRS as of 16-JAN-2024	450.08
		270 AFL as of 16-JAN-2024	330
		0 FLTS as of 04-JAN-2022	60

ENGINE NO. 1	SERIAL/PART: PCE-RV0757/3071016-01	MODEL: PT6A-66D	MANUFACTURER: PRATT & WHITNEY CANADA CORP.
	INSTALLED ON: 29-NOV-2021	LAST ACTUALS:	PROJECTED:
	0 ENG. HRS 0 A/C HRS	330.08 ENG. HRS as of 16-JAN-2024	450.08
	0 ENC	270 ENC as of 16-JAN-2024	330

PROPELLER NO. 1	SERIAL/PART: RJ627/HC-E5N-3C/NC8834K	MODEL: HC-E5N-3C	MANUFACTURER: HARTZELL PROPELLER INC.
	INSTALLED ON: 04-JAN-2022	LAST ACTUALS:	PROJECTED:
	0 PROP HRS 0 A/C HRS	330.08 PROP HRS as of 16-JAN-2024	450.08
	0 PRC		



New Requirement/Flagged Items

Operator Review and Action Required

Model: TBM 940 Serial: 1407 RegNo: N940LG HRS: 330.08 AFL: 270 As Of: 16-Jan-2024 Operator: LOVE AMERICA, LLC

Report Date: 23-Jan-2024

These tasks or requirements have been added newly to your aircraft status. Please review them and approve or modify as appropriate. Please pay particular attention to the Base and Next Due Times for these tasks. It is important to note that any task that has insufficient information (marked by ?), will never come due unless the necessary information is provided by you.

PN & SN	Effective Date	Unit	Interval	Base Time		Next Due (ENG/APU) A/C	Disposition
				Current	Change To		
SB 70-322-22		GSM86 SERVO ACTUATORS IMPROVEMENT, SERVICE BULLETIN					Bulletin ATA:22
	01-Jul-23	MOS	T:DUE	01-Jul-23	_____	01-Jul-24 * (M)	RECOMMENDED
		HRS			_____		
		AFL			_____		
NEW REQUIREMENT ADDED ON 14-DEC-23. RENEW BASE TIMES TO ENSURE CORRECT DUE TIMES.				REF: BULLETINS			
S930-230701		REVIEW TBM 930 MAINTENANCE MANUAL CHAPTER 5 REV. 008					Service ATA:00
	01-Jul-23	MOS	-	04-Jan-22	_____		REQUIREMENT CHANGE FORMS
		HRS			_____		
		AFL			_____		
NEW REQUIREMENT ADDED ON 19-DEC-23. RENEW BASE TIMES TO ENSURE CORRECT DUE TIMES.				REF: RCF S930			

Name: _____ Signature: _____ Cert.# _____ Date: _____

?-Insufficient Information S -Suppressed Requirement * -Estimated Due(New Requirement)(EFF) - Effective C/W M -Manual Due (EBT) - Estimated Base Time



Due List Report

Model: TBM 940 Serial: 1407 RegNo: N940LG HRS: 330.08 AFL: 270 As Of: 16-Jan-2024 Operator: LOVE AMERICA, LLC

Report Date: 23-Jan-2024

PN & SN	Unit	Interval	TSX/Adj.	C/W	Next Due (ENG/APU) A/C	Max. Limit	Remaining	Est. Due
SB 70-304-25		EMERGENCY EXIT DOOR OPENING, SERVICE BULLETIN						Bulletin ATA:25
	MOS	T:13		EFF	25-Aug-23 *		OVD	
	HRS							
	AFL							
Disposition: MANDATORY		REF: BULLETINS						
05-20-02		STANDARD PROGRAM - A INSPECTION						Package ATA:05
	MOS	12	Adj:-49d	22-Feb-23	04-Jan-24	04-Feb-24	TOL (+12 d)	23-Jan-2024(2)
	HRS	200		193	393	403	62.9 (+10)	
	AFL			193				
		REF: AMM 05-20-02 (A1)						
05-20-03		STANDARD PROGRAM - B INSPECTION						Package ATA:05
	MOS	24		04-Jan-22	04-Jan-24	04-Feb-24	TOL (+12 d)	23-Jan-2024
	HRS	400	Adj:-7	0	393	403	62.9 (+10)	
	AFL			0				
		REF: AMM 05-20-03 (A1)						
21-30-02-100-801		OUTFLOW VALVE - CLEAN VALVE SEAT						Service ATA:21
	MOS	24 (+10%/-10%)		04-Jan-22	04-Jan-24	16-Mar-24	TOL (+53 d)	23-Jan-2024
	HRS			0				
	AFL			0				
		REF: AMM 21-30-02 (A1)						
21-30-03-100-802		SAFETY VALVE - CLEAN VALVE SEAT						Service ATA:21
	MOS	24 (+10%/-10%)		04-Jan-22	04-Jan-24	16-Mar-24	TOL (+53 d)	23-Jan-2024
	HRS			0				
	AFL			0				
		REF: AMM 21-30-03 (A1)						
31-31-00-710-801		LIGHTWEIGHT DATA RECORDER - CHECK OPERATION						Service ATA:31
	MOS	24 (+10%/-10%)		04-Jan-22	04-Jan-24	16-Mar-24	TOL (+53 d)	23-Jan-2024
	HRS			0				
	AFL			0				
		REF: AMM 31-31-00 (A1)						
05-70-CA-890-801		NO. 1 ENGINE - MINOR INSPECTION						Package ATA:05
	MOS	12 (+1m)		22-Feb-23	22-Feb-24	22-Mar-24	30 d (+29)	22-Feb-2024
	HRS	200 (+10)		193	(393)393	403	62.9 (+10)	
	ENC			193				
		REF: EMM 72-00-00						

?-Insufficient Information S -Suppressed Requirement * -Estimated Due(New Requirement)(EFF) - Effective C/W M -Manual Due (EBT) - Estimated Base Time



Due List Report

Model: TBM 940 Serial: 1407 RegNo: N940LG HRS: 330.08 AFL: 270 As Of: 16-Jan-2024 Operator: LOVE AMERICA, LLC

Report Date: 23-Jan-2024

PN & SN	Unit	Interval	TSX/Adj.	C/W	Next Due (ENG/APU) A/C	Max. Limit	Remaining	Est. Due	
24-30-04-760-803		LEAD-ACID BATTERY - CHECK CAPACITY						Service	ATA:24
PN:RG-380E/44	MOS	12 (+1m/-1m)		22-Feb-23	22-Feb-24	22-Mar-24	30 d (+29)	22-Feb-2024	
SN:70016153	HRS	200 (+10%/-10%)		193	393	413	62.9 (+20)		
	AFL			193					
REF: AMM 24-30-04 (A1)									
61-00-00-200-802		NO. 1 PROPELLER - INSPECT EROSION SHIELD USING COIN-TAP						Service	ATA:61
	MOS	12			22-Feb-24 (M)		30 d	22-Feb-2024	
	HRS	600			(600)600 (M)		269.9		
REF:									
61-10-00-200-801		NO. 1 PROPELLER - PERFORM A PERIODIC INSPECTION						Service	ATA:61
	MOS	12		22-Feb-23	22-Feb-24		30 d	22-Feb-2024	
	HRS	400		193	(593)593		262.9		
REF: POM 61-00-47									
61-10-00-220-801		BETA RING AND CARBON BLOCK - DO A DIMENSIONAL CHECK						Service	ATA:61
	MOS	12 (+1m/-1m)		22-Feb-23	22-Feb-24	22-Mar-24	30 d (+29)	22-Feb-2024	
	HRS	600 (+10%/-10%)		193	793	853	462.9 (+60)		
	AFL			193					
REF:									
61-10-01-640-801		NO. 1 PROPELLER - PROPELLER - LUBRICATE						Service	ATA:61
	MOS	12		22-Feb-23	22-Feb-24		30 d	22-Feb-2024	
	HRS	400		193	(593)593		262.9		
REF: POM 61-00-47, AMM 61-10-01 (A1)									
61-10-01-640-802		NO. 1 PROPELLER - APPLY CORROSION INHIBITOR TO STEEL COUNTERWEIGHTS						Service	ATA:61
	MOS	12			22-Feb-24 (M)		30 d	22-Feb-2024	
	HRS	400			(400)400 (M)		69.9		
REF: POM 61-00-47									
79-00-CA-610-801		NO. 1 ENGINE - SERVICING OIL SYSTEM						Service	ATA:79
	MOS	12 (+1m)		22-Feb-23	22-Feb-24	22-Mar-24	30 d (+29)	22-Feb-2024	
	HRS			193					
	ENC			193					
REF: EMM 72-00-00									
79-20-02-710-801		NO. 1 ENGINE - CHIP DETECTORS - DO AN OPERATIONAL TEST						Service	ATA:79
	MOS	12 (+1m)		22-Feb-23	22-Feb-24	22-Mar-24	30 d (+29)	22-Feb-2024	
	HRS	600 (+10%)		193	(793)793	853	462.9 (+60)		
	ENC			193					
REF: EMM 79-20-02, AMM 72-00-00 (A1)									

Disposition: CPCP



Due List Report

Model: TBM 940 Serial: 1407 RegNo: N940LG HRS: 330.08 AFL: 270 As Of: 16-Jan-2024 Operator: LOVE AMERICA, LLC

Report Date: 23-Jan-2024

PN & SN	Unit	Interval	TSX/Adj.	C/W	Next Due (ENG/APU) A/C	Max. Limit	Remaining	Est. Due
SB 70-118-27 R02 PARA C		ACCOMPLISH, SERVICE BULLETIN CLEAN AND LUBRICATE THE ACTUATOR SCREW						Bulletin ATA:27
	MOS	12		EFF	22-Feb-24 * (M)		30 d	22-Feb-2024
	HRS	400		EFF	593 * (M)		262.9	
	AFL							
Disposition: MANDATORY		REF: BULLETINS						
05-20-05		ANNUAL INSPECTION						Package ATA:05
	MOS	12		22-Feb-23	29-Feb-24		37 d	29-Feb-2024
	HRS			193				
	AFL			193				
		REF: AMM 05-20-05 (A1)						
SB 70-256-71 R01		INERTIAL SEPARATOR DOOR SEAL, SERVICE BULLETIN						Bulletin ATA:71
	MOS	T:DUE		EFF	29-Feb-24 * (M)		37 d	29-Feb-2024
	HRS							
	AFL							
Disposition: RECOMMENDED		REF: BULLETINS						
SB 70-326-71		REPLACEMENT OF THE INERTIAL SEPARATOR (IPS) AFT LEVER, SERVICE BULLETIN						Bulletin ATA:71
	MOS				29-Feb-24 * (M)		37 d	29-Feb-2024
	HRS	T:633		EFF	633 *		302.9	
	AFL							
Disposition: RECOMMENDED		REF: BULLETINS						
FAA 2023-11-12		EMERGENCY EXIT TRIIM PANEL GRIPPING STRAP - MODIFICATION						AD ATA:52
	MOS	T:12		EFF	21-Jul-24 *		180 d	21-Jul-2024
	HRS							
	AFL							
Disposition: MANDATORY		REF: AD						
72-00-00-290-801		NO. 1 ENGINE - ENGINE - INSPECT HOT SECTION WITH BOROSCOPE						Service ATA:72
	MOS			04-Jan-22				22-Aug-2024
	HRS	400 (+10%)		0	(400)400	440	69.9 (+40)	
	ENC			0				
		REF: EMM 72-00-00						
73-10-05-790-801		NO. 1 ENGINE - FUEL MANIFOLD ADAPTERS - PERFORM LEAK TEST AND FUNCTION TEST						Service ATA:73
	MOS			04-Jan-22				22-Aug-2024
	HRS	400 (+10%)		0	(400)400	440	69.9 (+40)	
	ENC			0				
		REF: EMM 73-11-05						

?-Insufficient Information S -Suppressed Requirement * -Estimated Due(New Requirement)(EFF) - Effective C/W M -Manual Due (EBT) - Estimated Base Time



Due List Report

Model: TBM 940 Serial: 1407 RegNo: N940LG HRS: 330.08 AFL: 270 As Of: 16-Jan-2024 Operator: LOVE AMERICA, LLC

Report Date: 23-Jan-2024

PN & SN	Unit	Interval	TSX/Adj.	C/W	Next Due (ENG/APU) A/C	Max. Limit	Remaining	Est. Due	
74-00-CA-200-801		NO. 1 ENGINE - CHECK IGNITION EXCITER FOR INSTALLATION AND CONDITION						Service	ATA:74
	MOS			04-Jan-22				22-Aug-2024	
	HRS	400 (+10%)		0	(400)400	440	69.9 (+40)		
	ENC			0					
REF: EMM 74-10-00									
74-10-00-200-801		IGNITION EXCITER - CHECK FOR CONDITION AND ATTACHMENT						Service	ATA:74
	MOS			04-Jan-22				22-Aug-2024	
	HRS	400 (+10/-10)		0	400	410	69.9 (+10)		
	AFL			0					
REF: AMM 74-00-00 (A1)									
74-20-00-200-801		IGNITION CABLES - CHECK FOR ROUTING, ATTACHMENT AND WEAR DUE TO CHAFING						Service	ATA:74
	MOS			04-Jan-22				22-Aug-2024	
	HRS	400 (+10/-10)		0	400	410	69.9 (+10)		
	AFL			0					
REF: AMM 74-00-00 (A1)									
74-20-00-200-802		SPARK IGNITERS - CHECK FOR CLEANLINESS AND EROSION						Service	ATA:74
	MOS			04-Jan-22				22-Aug-2024	
	HRS	400 (+10/-10)		0	400	410	69.9 (+10)		
	AFL			0					
REF: GENERIC NO REF									
74-20-CA-200-802		NO. 1 ENGINE - CHECK SPARK IGNITERS FOR CLEANLINESS AND EROSION. CHECKFUNCTION						Service	ATA:74
	MOS			04-Jan-22				22-Aug-2024	
	HRS	400 (+10%)		0	(400)400	440	69.9 (+40)		
	ENC			0					
REF: EMM 74-20-00									
SB PT6A-72-14561		NO. 1 ENGINE - INSPECTION OF FUEL NOZZLE, SERVICE BULLETIN						Bulletin	ATA:72
	MOS							22-Aug-2024	
	HRS	T:400			(400)400		69.9		
	ENC								
REF: BULLETINS									