




Ministry of Tourism, Transportation & Labour

Department of Civil Aviation

ARUBA

CERTIFICATE OF ACCEPTANCE

| | |
|---|--|
| Name of holder: BANYAN AIR SERVICE | Address of holder: 5360 NW 20TH TERRACE, FORT LAUDERDALE U.S.A. |
| Location(s): 5360 NW 20th Terrace, Forth Lauderdale, U.S.A. | |
| It is hereby certified that in accordance with article 96, of the Regeling Luchtwaardigheid (AB 1995 no. 71, gewijzigd bij A.B. 2000 no. 58), the holder identified above has been approved for performing the following activities: Same as in the current Approval Certificate No. EASA.145.4235/ EASA.145.4281 issued by the European Aviation Safety Agency. | |
| Conditions / Limitations: 1. The same privileges, conditions and limitations as the EASA Part 145 Approval Certificate No. EASA.145.4235/ EASA.145.4281 apply; 2. Besides the regulations specified in the EASA PART 145 Approval Certificate No. EASA.145.4235/ EASA.145.4281, additional Aruba DCA regulations shall be complied with once issued; 3. Authorization reference DL-ACC-123 or EASA.145.4235/ EASA.145.4281 should be quoted as the authority in the appropriate records; 4. No scheduled maintenance shall be performed at other location(s) than those specified above without prior DCA Aruba approval; 5. Only parts and hardware traceable to the Original Equipment Manufacturer shall be installed on Aruban registered aircraft; 6. Subject to compliance with the foregoing conditions, this acceptance shall remain valid until the date of expiry mentioned below, unless the EASA.145.4235/ EASA.145.4281 approval has previously been surrendered, superseded, suspended or revoked. | |
| This acceptance is valid until: 06 July 2013 Revocation prior to this date remains reserved. Certificate no.: DL-ACC-123 Date of first issue: 08 July 2011 | Aruba, 08 July 2011 A.g. Director of Civil Aviation:  L.V. Reed |